

Useful FARO measurements for Image Transform

The most useful points to constrain the IMSE transform are sharp corners/edges visible during bright D α events.

21 points in order of usefulness:

1-5: Most useful

6-10 Useful

11-21 For extra accuracy
(some known already)

